Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00422

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: Chris Juliusson	Total Man Days: 3					
Pipeline Safety Representative(s): Donald Hankins						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	01/22/2016					

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Jerseyville	Donald Hankins	Jerseyville/Virden		9/10/2015, 9/8/2015, 9/9/2015	Chris Juliusson

Statement of Activities

On September 8-10, 2015, a field audit was conducted at Ameren Illinois, in Jerseyville, Illinois, to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

The audit included inspection of Ameren facilities including customer meters, cathodic protection, damage prevention, pressure limiting and regulating devices, valves and Odorization equipment

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00422

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]

ILPS #1